

Report No.: HS1203280170A RA No .: 0101174-E

Version: A

ESD (MACHINE MODE) TEST REPORT

Company : RAIO Technology Inc.

Model Name : RA8872

Date Code : <u>1122-N</u>

Date Received : MAR 28, 2012

Date Tested : MAR 30, 2012

TESTING LABORATORY IS ACCREDITED BY:

IEC/IECQ 17025 certificate of independent test laboratory approval

[🔛 Certificate No.: T1091

ISO 9001 certificate is approved by TUV CERT certification body of TUV NORD Cert GmbH

WE HEREBY CERTIFY THAT:

The test(s) shown in the attachment were conducted according to the indicating procedures. We assume full responsibility for the accuracy and completeness of these tests and vouch for the qualifications of all personnel performing them.

	Name	Name Signature		
Test Engineer	Brian Mao	Brian Mao	Mar 30, 2012	
Manager	Even Lin	Tunkie	Mar 30, 2012	

NOTE:

- 1. This report will be invalid if reproduced in whole or in part.
- 2. This report refers only to the specimen(s) submitted to test, and is invalid if used separately
- 3. This report is ONLY valid with the examination seal and signature of this institute.
- 4. The tested specimen(s) will only be preserved for thirty days from the state of the specimen of the specime collected by the applicant.
- 5. The failure criteria should be based on parametric and functional test provided in this report is for reference only.



Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-5770988

http://www.istgroup.com

Report No.: HS1203280170A RA No. : 0101174-E Page 1 of 8

TABLE OF CONTENTS

1. GENERAL INFORMATION	
1.1 DESCRIPTION OF UNIT	2
2. ESD (MACHINE MODE) TEST	
2.1 TEST EQUIPMENT	3
2.2 LABORATORY AMBIENCE CONDITION	3
2.3 REFERENCE DOCUMENT	3
2.4 TEST CONDITION	3
2.5 SUMMARY OF TEST	3
2.6 CONTENTS OF TEST	4



Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-5770988

http://www.istgroup.com

Report No.: HS1203280170A RA No. : 0101174-E Page 2 of 8

1. GENERAL INFORMATION

1.1 DESCRIPTION OF UNIT

MANUFACTURER : RAIO Technology Inc.

DEVICE NAME : RA8872

DATE CODE : 1122-N

PACKAGE / PIN COUNT : LQFP-100


REFERENCE DOCUMENT : JEDEC EIA/JESD22-A115

TEST VOLTAGE : 200V ~ 400V (±), Step: 100V (±)

SAMPLE QUANTITY : 18 ea

FAILURE CRITERIA : FOR V CHANGE AT 1µA ±30%

 $\mbox{\ensuremath{\not{\times}}}$ Failure Judgment: IV curve shift over 1µA±30% at forward point.



Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-5770988

http://www.istgroup.com

Report No.: HS1203280170A RA No.: 0101174-E

Page 3 of 8

2. ESD (MACHINE MODE) TEST

2.1 TEST EQUIPMENT

Test Equipment	Equipment Number	Tester	
KEYTEK ZAPMASTER	#5	02011	

2.2 LABORATORY AMBIENCE CONDITION

Temperature: 25±5°C

Relative humidity: 55%±10% (RH)

2.3 REFERENCE DOCUMENT

The test method refers to JEDEC EIA/JESD22-A115

2.4 TEST CONDITION

ALL - VSS (+)

ALL – VSS (-)

ALL – VCC (+)

ALL – VCC (-)

VCC - VSS (+)

VCC - VSS (-)

2.5 SUMMARY OF TEST

Test Model : MM	ESD Sensitivity	Passed : <u>±300V</u>	JI	EDEC Classification Class: B
Test condition	Sample Quantity	Passed Volts	Class A	: <200V.
ALL – VSS (+)	3	+400V	Class B	: \geq 200V , $<$ 400V
ALL – VSS (-)	3	-400V	Class C	: ≧400V
ALL – VCC (+)	3	+400V		
ALL – VCC (-)	3	-400V		
VCC – VSS (+)	3	+300V		
VCC – VSS (-)	3	-400V		

ALL:4-15,19-24,28-29,33-34,36-38,40-42,64-66, VCC:2,17-18,27,30,32,57,61,77,79-80 69-71,74,76,81-100 VSS:1,3,16,25,31,35,50-51,59,78

Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-5770988

http://www.istgroup.com

Report No.: HS1203280170A RA No.: 0101174-E

Page 4 of 8

2.6 CONTENTS OF TEST

ALL – VSS (+) (UNIT:V)							(UNIT:V)
Test FAIL Pin VOLTAGE	#1	#2	#3	Test FAIL Pin VOLTAGE	#1	#2	#3
4	PASS	PASS	PASS	64	PASS	PASS	PASS
5	PASS	PASS	PASS	65	PASS	PASS	PASS
6	PASS	PASS	PASS	66	PASS	PASS	PASS
7	PASS	PASS	PASS	69	PASS	PASS	PASS
8	PASS	PASS	PASS	70	PASS	PASS	PASS
9	PASS	PASS	PASS	71	PASS	PASS	PASS
10	PASS	PASS	PASS	74	PASS	PASS	PASS
11	PASS	PASS	PASS	76	PASS	PASS	PASS
12	PASS	PASS	PASS	81	PASS	PASS	PASS
13	PASS	PASS	PASS	82	PASS	PASS	PASS
14	PASS	PASS	PASS	83	PASS	PASS	PASS
15	PASS	PASS	PASS	84	PASS	PASS	PASS
19	PASS	PASS	PASS	85	PASS	PASS	PASS
20	PASS	PASS	PASS	86	PASS	PASS	PASS
21	PASS	PASS	PASS	87	PASS	PASS	PASS
22	PASS	PASS	PASS	88	PASS	PASS	PASS
23	PASS	PASS	PASS	89	PASS	PASS	PASS
24	PASS	PASS	PASS	90	PASS	PASS	PASS
28	PASS	PASS	PASS	91	PASS	PASS	PASS
29	PASS	PASS	PASS	92	PASS	PASS	PASS
33	PASS	PASS	PASS	93	PASS	PASS	PASS
34	PASS	PASS	PASS	94	PASS	PASS	PASS
36	PASS	PASS	PASS	95	PASS	PASS	PASS
37	PASS	PASS	PASS	96	PASS	PASS	PASS
38	PASS	PASS	PASS	97	PASS	PASS	PASS
40	PASS	PASS	PASS	98	PASS	PASS	PASS
41	PASS	PASS	PASS	99	PASS	PASS	PASS
42	PASS	PASS	PASS	100	PASS	PASS	PASS

Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-5770988

http://www.istgroup.com

Report No. : HS1203280170A RA No. : 0101174-E

Page 5 of 8

ALL – VSS (-)							(UNIT:V)
Test FAIL Pin VOLTAGE	#1	#2	#3	Test FAIL Pin VOLTAGE	#1	#2	#3
4	PASS	PASS	PASS	64	PASS	PASS	PASS
5	PASS	PASS	PASS	65	PASS	PASS	PASS
6	PASS	PASS	PASS	66	PASS	PASS	PASS
7	PASS	PASS	PASS	69	PASS	PASS	PASS
8	PASS	PASS	PASS	70	PASS	PASS	PASS
9	PASS	PASS	PASS	71	PASS	PASS	PASS
10	PASS	PASS	PASS	74	PASS	PASS	PASS
11	PASS	PASS	PASS	76	PASS	PASS	PASS
12	PASS	PASS	PASS	81	PASS	PASS	PASS
13	PASS	PASS	PASS	82	PASS	PASS	PASS
14	PASS	PASS	PASS	83	PASS	PASS	PASS
15	PASS	PASS	PASS	84	PASS	PASS	PASS
19	PASS	PASS	PASS	85	PASS	PASS	PASS
20	PASS	PASS	PASS	86	PASS	PASS	PASS
21	PASS	PASS	PASS	87	PASS	PASS	PASS
22	PASS	PASS	PASS	88	PASS	PASS	PASS
23	PASS	PASS	PASS	89	PASS	PASS	PASS
24	PASS	PASS	PASS	90	PASS	PASS	PASS
28	PASS	PASS	PASS	91	PASS	PASS	PASS
29	PASS	PASS	PASS	92	PASS	PASS	PASS
33	PASS	PASS	PASS	93	PASS	PASS	PASS
34	PASS	PASS	PASS	94	PASS	PASS	PASS
36	PASS	PASS	PASS	95	PASS	PASS	PASS
37	PASS	PASS	PASS	96	PASS	PASS	PASS
38	PASS	PASS	PASS	97	PASS	PASS	PASS
40	PASS	PASS	PASS	98	PASS	PASS	PASS
41	PASS	PASS	PASS	99	PASS	PASS	PASS
42	PASS	PASS	PASS	100	PASS	PASS	PASS

Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-5770988

http://www.istgroup.com

Report No. : HS1203280170A RA No. : 0101174-E

Page 6 of 8

ALL – VCC (+) (UNIT							(UNIT:V)
Test FAIL Pin VOLTAGE	#1	#2	#3	Test FAIL Pin VOLTAGE	#1	#2	#3
4	PASS	PASS	PASS	64	PASS	PASS	PASS
5	PASS	PASS	PASS	65	PASS	PASS	PASS
6	PASS	PASS	PASS	66	PASS	PASS	PASS
7	PASS	PASS	PASS	69	PASS	PASS	PASS
8	PASS	PASS	PASS	70	PASS	PASS	PASS
9	PASS	PASS	PASS	71	PASS	PASS	PASS
10	PASS	PASS	PASS	74	PASS	PASS	PASS
11	PASS	PASS	PASS	76	PASS	PASS	PASS
12	PASS	PASS	PASS	81	PASS	PASS	PASS
13	PASS	PASS	PASS	82	PASS	PASS	PASS
14	PASS	PASS	PASS	83	PASS	PASS	PASS
15	PASS	PASS	PASS	84	PASS	PASS	PASS
19	PASS	PASS	PASS	85	PASS	PASS	PASS
20	PASS	PASS	PASS	86	PASS	PASS	PASS
21	PASS	PASS	PASS	87	PASS	PASS	PASS
22	PASS	PASS	PASS	88	PASS	PASS	PASS
23	PASS	PASS	PASS	89	PASS	PASS	PASS
24	PASS	PASS	PASS	90	PASS	PASS	PASS
28	PASS	PASS	PASS	91	PASS	PASS	PASS
29	PASS	PASS	PASS	92	PASS	PASS	PASS
33	PASS	PASS	PASS	93	PASS	PASS	PASS
34	PASS	PASS	PASS	94	PASS	PASS	PASS
36	PASS	PASS	PASS	95	PASS	PASS	PASS
37	PASS	PASS	PASS	96	PASS	PASS	PASS
38	PASS	PASS	PASS	97	PASS	PASS	PASS
40	PASS	PASS	PASS	98	PASS	PASS	PASS
41	PASS	PASS	PASS	99	PASS	PASS	PASS
42	PASS	PASS	PASS	100	PASS	PASS	PASS

Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-5770988

http://www.istgroup.com

Report No. : HS1203280170A RA No. : 0101174-E

Page 7 of 8

ALL – VCC (-)						(UNIT:V)	
Test FAIL Pin VOLTAGE	#1	#2	#3	Test FAIL Pin VOLTAGE	#1	#2	#3
4	PASS	PASS	PASS	64	PASS	PASS	PASS
5	PASS	PASS	PASS	65	PASS	PASS	PASS
6	PASS	PASS	PASS	66	PASS	PASS	PASS
7	PASS	PASS	PASS	69	PASS	PASS	PASS
8	PASS	PASS	PASS	70	PASS	PASS	PASS
9	PASS	PASS	PASS	71	PASS	PASS	PASS
10	PASS	PASS	PASS	74	PASS	PASS	PASS
11	PASS	PASS	PASS	76	PASS	PASS	PASS
12	PASS	PASS	PASS	81	PASS	PASS	PASS
13	PASS	PASS	PASS	82	PASS	PASS	PASS
14	PASS	PASS	PASS	83	PASS	PASS	PASS
15	PASS	PASS	PASS	84	PASS	PASS	PASS
19	PASS	PASS	PASS	85	PASS	PASS	PASS
20	PASS	PASS	PASS	86	PASS	PASS	PASS
21	PASS	PASS	PASS	87	PASS	PASS	PASS
22	PASS	PASS	PASS	88	PASS	PASS	PASS
23	PASS	PASS	PASS	89	PASS	PASS	PASS
24	PASS	PASS	PASS	90	PASS	PASS	PASS
28	PASS	PASS	PASS	91	PASS	PASS	PASS
29	PASS	PASS	PASS	92	PASS	PASS	PASS
33	PASS	PASS	PASS	93	PASS	PASS	PASS
34	PASS	PASS	PASS	94	PASS	PASS	PASS
36	PASS	PASS	PASS	95	PASS	PASS	PASS
37	PASS	PASS	PASS	96	PASS	PASS	PASS
38	PASS	PASS	PASS	97	PASS	PASS	PASS
40	PASS	PASS	PASS	98	PASS	PASS	PASS
41	PASS	PASS	PASS	99	PASS	PASS	PASS
42	PASS	PASS	PASS	100	PASS	PASS	PASS

Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-5770988

http://www.istgroup.com

Report No.: HS1203280170A RA No.: 0101174-E Page 8 of 8

	(UNIT: V)		
Test FAIL Pin VOLTAGE	#1	#2	#3
2	PASS	PASS	PASS
17	PASS	PASS	PASS
18	PASS	PASS	400
27	PASS	400	400
30	PASS	PASS	PASS
32	PASS	PASS	400
57	PASS	PASS	PASS
61	PASS	PASS	PASS
77	PASS	PASS	PASS
79	PASS	PASS	PASS
80	PASS	PASS	PASS

	(UNIT: V)		
Test FAIL Pin VOLTAGE	#1	#2	#3
2	PASS	PASS	PASS
17	PASS	PASS	PASS
18	PASS	PASS	PASS
27	PASS	PASS	PASS
30	PASS	PASS	PASS
32	PASS	PASS	PASS
57	PASS	PASS	PASS
61	PASS	PASS	PASS
77	PASS	PASS	PASS
79	PASS	PASS	PASS
80	PASS	PASS	PASS